

#	LISTING OF FORENSIC INVESTIGATIONS		TYPE
1	Crane Company	45MVA Transformer "Slipped" at Steel Plant	Electrical
2	Ins. Co.	Barn Loft Collapse	Structure
3	Ins. Co.	Pool Sediment Investigation	Water/Chem.
4	Ins. Co.	Multiple Building Damage	Structure
5	Architectural Firm	Apt. Moisture Infiltration Evaluation	Water
6	Ins. Co.	Hot Water Pipe Rupture	Water
7	Ins. Co.	Residential House Fire	Fire
8	Ins. Co.	Residential Garage Fire	Fire
9	Ins. Co.	Failed Apt. Water Cooler	Water
10	Ins. Co.	Combination Washer/Dryer Overflow	Elec./Mech.
11	Ins. Co.	Apartment Chimney Fire	Fire
12	Ins. Co.	Children's Hospital Water Treatment	Water/Chem.
13	Adjuster	Failed Grain Feed Pipes	Structure
14	Ins. Co.	Metal Roofing Evaluation	Structure
15	Property Owner	Apt. Fire Investigation - 2 fatalities	Fire
16	Ins. Co.	Hospital - Variable Frequency Drive Fire	Fire
17	Ins. Co.	Private Girls School - Boiler Inspection	Elec./Mech.
18	Adjuster	18 Wheeler Cab Engine Fire	Fire
19	Ins. Co.	Garage Roof Deflection	Structure
20	Ins. Co.	Residential Fire	Fire
21	Ins. Co.	Residential Fire	Fire
22	Ins. Co.	Residential Hail Damage	Structure
23	Ins. Co.	Residential Fire	Fire
24	Ins. Co.	Residential Fire	Fire
25	Ins. Co.	Residential Fire	Fire
26	Re-Ins. Co.	Apt. Building Hot Water Heater Failure	Water
27	Property Owner	Expert Review of existing Forensic report	Consult
28	Ins. Co.	Residential Fire	Fire
29	Ins. Co.	McDonald's Fryer Fire	Fire
30	Ins. Co.	Automobile Theft Investigation	Elec./Mech.
31	Ins. Co.	Automobile Engine Fire	Fire
32	Ins. Co.	Residential Water Damage	Water
33	Ins. Co.	18 wheeler/pickup truck accident - 1 fatality	Accident
34	Ins. Co.	Investigation of 1MVA Transformer failure	Electrical
35	Ins. Co.	Driveway cracking investigation	Structure